


Monument and memorial condition survey



This survey is not a safety survey. Such surveys are the responsibility of the Church and should be carried out by professionally qualified people.

Name of cemetery or burial ground: ST PETERS HEYSHAM		Date: 23/9/22 Time: 4.00pm	
Name of earliest burial RICHARD CARTMEL	Section A	GPS N 54.04765 W 002.90186	
	Memorial type Convex shoulders with ornamentation with kerb	Dimensions (mm) H 1620 W 1000 D 2140	
Dates June 21st 1905	Mason or sculptor NONE		
Inscription In loving memory of my dear husband Richard Cartmel, who was drowned at Heysham Harbour June 21st 1905 aged 24 years. Boast not thyself of tomorrow for thou knowest not what a day may bring forth. Proverbs XXVII.1. A sudden change, and in a moment fell, and had no time to bid my friends farewell, think nothing strange, death happens unto the all. My lot today, tomorrow you may fall.		Principal material (circle) Limestone <u>Granite</u> Sandstone Marble Slate Brick Bronze Iron Lead	
		Type of inscription (circle) <u>Incised</u> Filled Painted Lead Raised Mortar	
		Ground condition (circle) <u>Good/level</u> Subsiding Collapsed Uneven	
Overall structural condition (circle) <u>Sound</u> Tilted Disrupted Fallen Collapsed Laid flat		Details Convex shoulders with ornamentation, floral carving and red granite pillars. Plumed top. Black granite base with some incised ornamentation. Kerbs visible on 2 sides, one buried by turf.	
Type of deterioration (circle) NONE		Surface condition (circle) <u>Surface dirt</u> Organic growth	Condition of inscription <u>Legible</u> Part legible
Loose elements Missing elements Cracking		Graffiti Delamination	Illegible Obscured
Damage from cramps Disruption Open joints		Powdering/spalling Eroded	Faded
Cracked pointing			